




What types of information needs to be on my design sketches?

How do I show dimensions (size)?

Lines and arrows to show length, width, height & wheelbase. Measurements show size of product, not sketch.

How do I show materials?

Lines and arrows drawn to each part with materials labeled.



Oct 12-7:52 AM

final slide



Which solution is the best choice?

What is a PRO and what is a CON?

PRO = The specification is met and shown on sketch.

CON = The specification is NOT met or NOT shown on sketch

Do my measurements/sizes make sense? How can I check?

Use a ruler to check measurements and compare to design specs.

Oct 12-7:52 AM